


ANOTHER SOLUTION FROM AMERICAN METER


HOW MUCH TIME AND MONEY DOES THIS PROBLEM
COST YOUR COMPANY?

PROBLEM →



Utilities across the country have told us one of the problems they face every day is dealing with Index Boxes that have yellowed and hazed to the point that Meter Readers can't read them. This causes misreads,

no reads, and the labor and material costs associated with replacing the Index Box and gasket. Until now, the polycarbonate technology available to the industry wasn't able to offer a solution.



← **SOLUTION**

American Meter Company now offers an Index Box with a protective hardcoating to eliminate this yellowing problem. The above half-coated Index Box illustrates the

effectiveness of this new technology. For more information on this unique, cost-saving feature contact your local American Meter Company representative.

 **AMERICAN
METER COMPANY**

The Clear Choice!

215-830-1800